

Activity Risk Assessment		BLACK HOLE	
Date of Initial Assessment	30 th January 2010	Date of Initial Management Committee Approval	30 th January 2010
Latest assessment review	1 st February 2025	Review approved and issued by Management Committee	1 st February 2026
Signature	JP	Signature	PEC

Hazards	Existing Control Measures	Who is at risk?	Comments/Notes
	<p>This activity is self-run by the visiting group leaders. The information below is provided to assist the groups' responsible leaders in the preparation of their own documented Risk Assessment</p> <p>Our risk assessment cannot take in to account the competence of the supervision nor the ability, medical condition, or attitude of the participants.</p> <p>It is expected that the factors below will be considered by the groups' responsible leader when completing their own documented Risk Assessment before and during use of the activity</p>		
Major collapse of Structure	The structure of the Black Hole is inspected during the closed season each year	Participants, campers, members of the public	
Panic by Participant	The Emergency exits must be unlocked and an adult stationed by the exits to listen for sign of distress from the participants		
Wood splinter	Monthly inspections – Gloves have been considered but not though necessary	Participant	
Head injury	Helmet are provided for the participants to wear when using the Black hole to prevent knock to the head.	Participant	
Injury due to overcrowding of the Black Hole	Maximum occupancy is advised, and activity supervised by leaders.	Participants	
Third Party Injury	The structure is locked when the activity isn't being used so access is prevented to all, and wildlife.	Members of the Public, Campers	

Reviewed: 1 st February 2025	By: The Oaks Management Committee
---	-----------------------------------